


MOC-One™ Conformance Service – Case History 1

Challenge

- Oil well, highly fractured reservoir
- Horizontal openhole completion
- Strong aquifer support
- Watered out fracture, watercut ~50%, well is not flowing anymore




Solution

- 5 m³ of MOC-One through 1 3/4" CT

Results

- Watercut reduced by 10%
- Well is producing by itself.



SPE113700

HALLIBURTON