

# CASE STUDY: BG DYNAMIC ENGINE RESTORATION SERVICE

## **SERVICE** BG Dynamic Engine Restoration Service

PRODUCTSBG Dynamic Engine Cleaner, PN 103192BG Dynamic Engine Cleaner Rinse Oil, PN PE04-N1GABG Platinum® 44K®, PN 208BG Advanced Formula MOA®, PN 115



VEHICLE: 2017 Infiniti QX80 28,000 miles (45,062 km)

# PROBLEM

The vehicle had never had an oil change, extremely low oil pressure, sludge buildup, and oil cooler sludge buildup.

# SOLUTION


The BG Dynamic Engine Restoration Service: a powerful, safe engine and fuel system cleaning service.

### Features

- Removes oil sludge and varnish
- Restores compression
- Harmless to oil pumps, seals, and gaskets

### **Benefits:**

- · Lowers tailpipe emissions
- Reduces oil consumption
- Improves overall power and engine efficiency




© copyright 2021 BG Products, Inc. • Wichita, Kansas 67213 • The information contained herein based on BG Products, Inc., best professional judgment. The information is intended for the use of the individual or entity named on the report. Any dissemination to third parties is unauthorized. If you have received this information in error, please notify us immediately by telephone (1-888-570-0842) and we will arrange for the return of the original paperwork to our office. Disclosure, copying, distribution or use of the contents strictly prohibited.



Continued

## SERVICE RESULTS

DIPSTICK





BEFORE

Check engine code was cleared and has yet to reappear. Engine was saved, and it's functioning like normal. Dealer recommended replacing the engine, a total investment of \$18,000.

The BG Dynamic Engine Restoration Service helped the owner save money.

Field Case Study submitted by: SPS of DFW Chris Murphy's Automotive, Dallas, TX

© copyright 2021 BG Products, Inc. • Wichita, Kansas 67213 • The information contained herein based on BG Products, Inc., best professional judgment. The information is intended for the use of the individual or entity named on the report. Any dissemination to third parties is unauthorized. If you have received this information in error, please notify us immediately by telephone (1-888-570-0842) and we will arrange for the return of the original paperwork to our office. Disclosure, copying, distribution or use of the contents strictly prohibited. R00