

CrystalSeal[®] Conformance Service – Case History 1

Challenge

- US – Permian - CO₂ EOR project
- Interwell communication / out-of-zone injection, due to highly eroded channels

Solution

- CrystalSeal[®] bullheaded into the WAG injection well
- Two stages were deployed until a significant pressure response was achieved.

Results

- Improved injectivity profile

